


## The Exploding Fishhook





- A fishhook explodes during a fishing trip and the final resting place is inside the client's skull.
- Analysis showed a wide variation in manufacturing and final hook properties.
- The matter would have been litigated based upon lack of quality control.

## **Attorney Referral**

I am pleased to provide this letter of recommendation reflecting the excellent work that you performed on the unique products liability case involving the defective fishhook. Your work was thorough and extremely competent in all technical areas involving metallurgy. I was impressed with your cooperative attitude and very prompt replies to all my inquiries. I also appreciated and admired your dedicated and systematic examination of all potential theories of liability and your willingness to prepare exhaustively for cross examination.