

The Untested Knee Joint





- A plastic portion of a knee joint begins to disintegrate while in use.
- Examination revealed delamination or separation of the plastic caused by a change in manufacturing practice.
- The matter was successfully litigated based upon inadequate product testing prior to introduction of the manufacturing change.

Attorney Referral

Mr. John Sauer, who testified on behalf of the plaintiffs, was an important asset to the Plaintiffs presentation of the case. He was very well prepared and familiar with the documents produced in the litigation and in fact, had greater familiarity with the details of the knee implant than did the engineers employed by the Defendant company. His thorough preparation and poise on the witness stand was instrumental in obtaining a verdict on behalf of the Plaintiffs in the case.